



4th December 2007

Auckland Regional Council  
Private Bag 92 012  
Auckland.

**Attention: Naveen Kumar, Water Resources Section**

**Re: Three Kings Quarry De-watering Consent 12977**


Dear Naveen

As required by Condition 7 of the above resource consent, please find enclosed records of groundwater level measurements for the period of 1 September 2007 to 30 November 2007.

Please note that the groundwater level within bore 2B was not measured in September and October as access to this bore has not been possible as the quarry floor around the bore has been flooded following the winter rains. Bore 5B was taken as the quarry reference bore until bore 2B was able to be read.

I trust all is in order. Please contact the undersigned if any further information or clarification is required.

Yours faithfully  
for **Winstone Aggregates**

  
Michael Harris  
Engineering Geologist.

**THREE KINGS QUARRY**  
**RESOURCE CONSENT 12977**  
**QUARTERLY REPORT**

**December 2007**

**QUARTERLY REPORT**  
**THREE KING QUARRY – RESOURCE CONSENT 12977**

The following report is made with regard to Condition 7 of Resource Consent 12977.

This report contains the groundwater levels within boreholes surrounding the take point.

A plan showing the location of boreholes in which groundwater levels were measured is attached.

This report contains records for the period of the 1st September to 30th November 2007.



