




Differential Settlement Alarm Trend Analysis







Differential Settlement Alarm Trend – Smallfield Avenue




Differential Settlement Alarm Trends – Mt Albert Road




Differential Settlement Alarm Trends
Marie Ave / Hillsborough Road / Budock Road





Differential Settlement Trend Analysis - AP92 vs AP93







Differential Settlement Trend Analysis - AP80 vs AP92







Differential Settlement Trend Analysis - AP62A vs AP88A







Differential Settlement Trend Analysis - AP110 vs AP111







Differential Settlement Trend Analysis - OCP68 vs AP114













Differential Settlement Trend Analysis - AP115 vs AP116







Differential Settlement Trend Analysis - AP70 vs AP117






Differential Settlement Trend Analysis - AP38 vs AP117







Differential Settlement Trend Analysis - AP70 vs AP117




Adjusted Settlement (mm)





Differential Settlement Trend Analysis - BP1977 vs AP71






Differential Settlement Trend Analysis - RM3900 vs RM3901






Differential Settlement Trend Analysis - RM3901 vs RM3902



Adjusted Settlements (mm)



Differential Settlement Trend Analysis - OCP90B vs SM6241

