

Quarry and Fill Operations Report


28th August 2017



Note: The future plan is indicative only and subject to change

Volume of Fill

Volume of Fill Tipped Per Month (tonnes)



Pest Control



Possum traps and rat baits:

- Continue to be checked and baited
- 1 possum was caught since last meeting in Zone 1.

Incidents / Complaints Review

DATE:

12/08/2017

SUMMARY OF ISSUE:

Call received from a member of the public regarding trucks observed driving through Mt Eden Village to/from Three Kings Quarry


SUMMARY OF ACTION:

Email was sent out to all clients currently carting fill to Three Kings Quarry to request truck drivers use Gillies Ave and Balmoral Rd as primary route to/from Three Kings Quarry whenever possible. Gleeson & Cox Transport responded that they have been issued HPMV permits which specifically state that they must use Mt Eden Road to cart to/from the quarry.

Deep Fill Weighted Rolling Mean

1 of 4


% Result of Weighted Criteria



Deep Fill Weighted Rolling Mean

2 of 4


% Result of Weighted Criteria



Deep Fill Weighted Rolling Mean

3 of 4


% Result of Weighted Criteria



Deep Fill Weighted Rolling Mean

4 of 4


% Result of Weighted Criteria



Shallow Fill Weighted Rolling Mean

1 of 4


% Result of Weighted Criteria



Shallow Fill Weighted Rolling Mean

2 of 4


% Result of Weighted Criteria



Shallow Fill Weighted Rolling Mean

3 of 4


% Result of Weighted Criteria



Shallow Fill Weighted Rolling Mean

4 of 4

% Result of Weighted Criteria



Thank you.
That concludes the
August 2017 Quarry & Fill
Operations Report